

& coolkidsbouncycastle.com



ANNUAL SAFETY INSPECTION REPORT


Tel: 07928 678577

2396

Structure	P	F	N/A
Security of Seams	✓		
Stitching	✓		
Anchor Points	✓		
Anchor Accessories	✓		
Walls & Towers	✓		
Blower Distance	✓		
Zip(s)	✓		
Fabric Flame Retardant	✓		
Fabric Strength	✓		
Step/Ramp Size			✓
Grounding			✓
Sharp Angles & Edges	✓		
Stability	✓		
Ropes			✓
Artwork to EN71-3?			
(Supplier/Importer must provide certificates for new equipment)	✓		
Air Loss Points	✓		
Water Gauge Pressure	✓		
Fall On Height			✓
Travel Depth			✓
Threat	✓		
Heating			✓
Entrapment	✓		
Deflation/Evacuation Time	✓		
Windows			✓
Markings	✓		
Identification	✓		

Totally Enclosed Structures

- Exits
- Exit Markings
- Lighting Supports
- Emergency Lighting
- Deflation Speed
- User Area Pressure



Slides
Wall Heights
Run Out
Clamber Net
Slide Sheet

Blower			
Size & Type	✓		
Inlet & Outlet Mesh	✓		
Cable & Plug	✓		
Casing & Impeller	✓		
Pat Test	✓		
Return Flap	✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Notes/Risk Assessment

GIBBONS 1.5HP DB8B

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print: