

& coolkidsbouncycastle.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2363

Structure	P	F	N/A
Security of Seams	✓		
Stitching	✓		
Anchor Points	✓		
Anchor Accessories	✓		
Walls & Towers	✓		
Blower Distance	✓		
Zip(s)	✓		
Fabric Flame Retardant	✓		
Fabric Strength	✓		
Step/Ramp Size	✓		
Grounding	✓		
Sharp Angles & Edges	✓		
Stability	✓		
Ropes	✓		
Artwork to EN71-3?			
(Supplier/Importer must provide certificates for new equipment)	✓		
Air Loss Points	✓		
Water Gauge Pressure	✓		
Fall Off Height	✓		
Trough Depth	✓		
Thread	✓		
Netting	✓		
Equipment	✓		
Distortion/relaxation Time	✓		
Windows			✓
Markings	✓		
Identification	✓		

Totally Enclosed Structures
Exits
Exit Markings
Lighting Supports
Emergency Lighting
Deflation Speed
User Area Pressure

Slides
Wall Heights
Run Out
Clamber Net
Slide Sheet

Blower			
Size & Type	✓		
Inlet & Outlet Mesh	✓		
Cable & Plug	✓		
Casing & Impeller	✓		
Pat Test	✓		
Return Flap	✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Notes/Risk Assessment

1-5 HP Brown OLSA-

ONE USER AT A TIME, PILLOW MUST BE ALLOWED TO FULLY INITIALIZE BEFORE NEXT USER, REFER TO MAINTENANCE OPERATIONS MANUAL.

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print: