

GSB Inflatable Inspections

& coolkidsbouncycastleles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2367

Structure

Security of Seams
Stitching
Anchor Points
Anchor Accessories
Walls & Towers
Blower Distance
Zip(s)
Fabric Flame Retardant
Fabric Strength
Step/Ramp Size
Grounding
Sharp Angles & Edges
Stability
Ropes
Artwork to EN71-3?
(Supplier/Importer must provide certificates for new equipment)
Air Loss Points
Water Gauge Pressure
Fall Off Height
Trough Depth
Thread
Netting
Entertainment
Deflation/Evacuation Time
Windows
Markings
Identification

P	F	N/A
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
✓		
		✓
✓		
✓		
✓		
✓		
✓		✓
✓		
✓		✓
✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Paxo

DB8823C

2023

Bounce Run

Black / Red

10.3 x 3.55 x 2.7m

Two


1.7m

7th August 2025 Twenty Five

6th August 2026 Twenty Six


Totally Enclosed Structures

Exits
Exit Markings
Lighting Supports
Emergency Lighting
Deflation Speed
User Area Pressure



Slides

Wall Heights
Run Out
Clamber Net
Slide Sheet



Blower

Size & Type
Inlet & Outlet Mesh
Cable & Plug
Casing & Impeller
Pat Test
Return Flap

✓		
✓		
✓		
✓		
✓		
✓		

Notes/Risk Assessment

1-5HP Blower D2SE

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print:

C. Bonehill

C. Bonehill