GSB Inflatable Inspections

& coolkidsbouncycastles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2364

Structure	P	F	N/A
Security of Seams	/		
Stitching	V		
Anchor Points	V		
Anchor Accessories	V		
Walls & Towers	V		
Blower Distance	V		
Zip(s)	V		
Fabric Flame Retardant	1/		
Fabric Strength	V		
Step/Ramp Size	V		
Grounding	/		
Sharp Angles & Edges	1		
Stability			
Ropes			1
Artwork to EN71-3?			V
(Supplier/Importer must provide			1
certificates for new equipment)			V
Air Loss Points	1		
Water Gauge Pressure	1		
Fall Off Height	V		
Trough Depth	V		
Thread	V		
Netting	~		1
			/
Entrapment Proposition Tona	V		
Deflation/Evacuation Time Windows	-		-
			/
Markings	1	36.13	
lossification			
			,
Totally Englaced Structures			1
Edis			/
Exit Markings	1	1	
Lighting Supports		100	
Emergency Lighting	/	1	
Deflation Speed	/		
User Area Pressure			
Oli Ia			
Slides			/
Wall Heights	1	-	
Run Out	13	/	
Clamber Net		K	
Slide Sheet			
Planner			
Blower	/		
Size & Type	V		
Inlet & Outlet Mesh	V		
Cable & Plug			
Casing & Impeller	V		
Pat Test	1		
Return Flap	/		

Manufactured by:	YASCO
Serial Number	98231
Year Made:	2023
Description of Unit:	Chromor Bro
Colour:	Blade Rea
Size:	6+6+1-9m
Max No. Users:	Two
Max User Height:	1.54.
Date Issued:	7th Avant 2025 Thought
Expiry Date:	6+14 Avenus 2026 Tweetysix

Notes/Risk	Assessmen	t	
1-Sitt	Blown	D256.	
AL.			Same

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Cianad.	\a. \	Soulit	Dulanta	G. DONEHILL
Signed:	V 1	(Dw	Print:	O +0,