

& coolkidsbouncycastleles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2391

Structure	P	F	N/A
Security of Seams	✓		
Stitching	✓		
Anchor Points	✓		
Anchor Accessories	✓		
Walls & Towers	✓		
Blower Distance	✓		
Zip(s)	✓		
Fabric Flame Retardant	✓		
Fabric Strength	✓		
Step/Ramp Size	✓		
Grounding	✓		
Sharp Angles & Edges	✓		
Stability	✓		
Ropes	✓		
Artwork to EN71-3? (Supplier/Importer must provide certificates for new equipment)			✓
Air Loss Points	✓		
Water Gauge Pressure	✓		
Fall Off Height	✓		
Trough Depth	✓		
Thread	✓		
Netting	✓		
Entrapment	✓		
Deflation/Evacuation Time	✓		
Windows			✓
Markings	✓		
Identification	✓		
Totally Enclosed Structures			
Exits			
Exit Markings			
Lighting Supports			
Emergency Lighting			
Deflation Speed			
User Area Pressure			
Slides			
Wall Heights			
Run Out			
Clamber Net			
Slide Sheet			
Blower			
Size & Type	✓		
Inlet & Outlet Mesh	✓		
Cable & Plug	✓		
Casing & Impeller	✓		
Pat Test	✓		
Return Flap	✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Notes/Risk Assessment

2HP Blower DB8D.

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print: