GSB Inflatable Inspections

& coolkidsbouncycastles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2385

Structure	Р	F	N/A
Security of Seams	1		
Stitching	V		
Anchor Points	V		
Anchor Accessories			
Walls & Towers	V		
Blower Distance	V		
Zip(s)			1
Fabric Flame Retardant	1		
Fabric Strength	/		
Step/Ramp Size	/		
Grounding			/
Sharp Angles & Edges	1		
Stability	1		
Ropes			/
Artwork to EN71-3?			
(Supplier/Importer must provide			/
certificates for new equipment)			~
Air Loss Points	1		
Water Gauge Pressure	1		
Fall Off Height	1		
Trough Depth			/
Thread	1		-
Nathing	-/		
Envaporant	1		
Defision/Evacuation Time	-		
MADORS .	~		/
Markings	-		/
Identification	1		
Idontification			
Totally Enclosed Structures			
Exits			
Exit Markings		1	
Lighting Supports		1	
Emergency Lighting		/	
Deflation Speed	1		1
User Area Pressure			
OSCI / II CA I TOSSUIC			
Slides			
Wall Heights		1	/
Run Out	1	-	
Clamber Net		A	
Slide Sheet	/	JA.	
Olide Olieet			
Blower			
	1		
Size & Type	/		
Inlet & Outlet Mesh	-		
Cable & Plug	-		
Casing & Impeller			
Pat Test	1		
Return Flap			

Manufactured by:	Orthogo.			
Serial Number	DB1125.			
Year Made:	2016			
Description of Unit:	HUMAN FOOTBALL TABLE			
Colour:	Cheen/ Yaron			
Size:	12.6+7.6+2.lm.			
Max No. Users:	Tiela			
Max User Height:	1.8n.			
Date Issued:	11th August 2025 Twenty The			
Expiry Date:	LOTH AUGUST 2026 Tratysus			

Notes/Risk Assessment			
1.548	Biown	DB12.	

This annual report confirms the equipment identified above was	tested and conformed to EN14960-2019 Standards
at the time of test, however it does not confirm the equipment	will continue to conform to the above standard for
at the time of test, however it does not confirm the equipment the full 12 months prior to the expery date.	2 1

Signed:	Soulth	Print:	Solfen
---------	--------	--------	--------