

GSB Inflatable Inspections

& coolkidsbouncycastleles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577

2371

Structure

	P	F	N/A
Security of Seams	✓		
Stitching	✓		
Anchor Points	✓		
Anchor Accessories	✓		
Walls & Towers	✓		
Blower Distance	✓		
Zip(s)	✓		
Fabric Flame Retardant	✓		
Fabric Strength	✓		
Step/Ramp Size	✓		
Grounding			✓
Sharp Angles & Edges	✓		
Stability	✓		
Ropes			✓
Artwork to EN71-3?			
(Supplier/Importer must provide certificates for new equipment)	✓		
Air Loss Points	✓		
Water Gauge Pressure	✓		
Pat. On Material	✓		
Trough Depth			✓
Thread	✓		
Netting			✓
Entrapment	✓		
Deflation/Evacuation Time	✓		
Windows			✓
Markings	✓		
Identification	✓		

Totally Enclosed Structures

Exits	✓		
Exit Markings	✓		
Lighting Supports			✓
Emergency Lighting			✓
Deflation Speed	✓		
User Area Pressure	✓		

Slides

Wall Heights			
Run Out			
Clamber Net			
Slide Sheet			

Blower

Size & Type	✓		
Inlet & Outlet Mesh	✓		
Cable & Plug	✓		
Casing & Impeller	✓		
Pat Test	✓		
Return Flap	✓		

Manufactured by:

Serial Number

Year Made:

Description of Unit:

Colour:

Size:

Max No. Users:

Max User Height:

Date Issued:

Expiry Date:

Airmax

P60288

2025

LASER MASC

Black/Green

10.65 x 9.85 x 2.3m

Six

1.8m.

7th August 2025 Judy He

6th August 2026 Judy Six

Notes/Risk Assessment

Noted Black 1HP DB6A.

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:

Print: