GSB Inflatable Inspections

& coolkidsbouncycastles.com



ANNUAL SAFETY INSPECTION REPORT

Tel: 07928 678577 2393

Structure	Р	F	N/A
Security of Seams	V		
Stitching		/	
Anchor Points	V		
Anchor Accessories	V		
Walls & Towers			/
Blower Distance	9 22 11 11		/
Zip(s)			/
Fabric Flame Retardant	1		
Fabric Strength	1		
Step/Ramp Size			/
Grounding			/
Sharp Angles & Edges	1		
Stability	/		
Ropes			1
Artwork to EN71-3?			_
(Supplier/Importer must provide	1		
certificates for new equipment)	/		
Air Loss Points	1		
Water Gauge Pressure	-		/
Fall Off Height			./
Trough Depth		The Market	-
Thread			./
Netting			1
Entragment	./		
Desarron/Evecuation Time	1		
Sympleys		1	/
Waitings	1		-
Centification	1		
administration			
Totally Enclosed Structures			1
Exits			
Exit Markings			
Lighting Supports	1	1	
Emergency Lighting		N	
Deflation Speed	/		
User Area Pressure	/		
Slides			1
Wall Heights		1	
Run Out	1) /	
Clamber Net	/	A	
Slide Sheet	/		
DI-			
Blower	1		
Size & Type	~		,
Inlet & Outlet Mesh			/
Cable & Plug	V		,
Casing & Impeller			/
Pat Test	~		1
Return Flap	٧		/

Manufactured by:	りならのシ
Serial Number	DB3823U
Year Made:	2019.
Description of Unit:	INGLECTION CAME
	Clued Bist.
Colour:	Marie Constitution of the
Size:	2641.1 x035m.
Max No. Users:	Tio
Max User Height:	1-31.
Date Issued:	11th Avans 2025 Tuety The
Expiry Date:	LOW AUGUST 2026 Twely SIX

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to the expiry date.

Signed:	(Sould	Print:	G. Barren