## **GSB** Inflatable Inspections

## & coolkidsbouncycastles.com



Tel: 07928 678577

## ANNUAL SAFETY INSPECTION REPORT

Structure	Р	F	N/A		2379
Structure Security of Seams Stitching Anchor Points Anchor Accessories Walls & Towers Blower Distance Zip(s) Fabric Flame Retardant Fabric Strength Step/Ramp Size Grounding Sharp Angles & Edges Stability Ropes Artwork to EN71-3?	P V V V V V V V V V V V	F	N/A	Manufactured by: Serial Number Year Made: Description of Unit: Colour:	MAGIC AIR. MADGRESITS  ZO23  VIRE OUT BO  H MECHANICA NOT TERO*
(Supplier/Importer must provide certificates for new equipment) Air Loss Points Water George Pressure Feli QX (Feligial Trough Benin) Trough Benin Trough Benin Trough Benin Defiation/Evacuation Time Windows Markings Identification	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\			Size: Max No. Users: Max User Height: Date Issued: Expiry Date:  Notes/Risk Assessr	nent
Totally Enclosed Structures Exits Exit Markings Lighting Supports Emergency Lighting Deflation Speed User Area Pressure  Slides		3	A		
Wall Heights Run Out Clamber Net Slide Sheet  Blower Size & Type Inlet & Outlet Mesh	V V	1	X		
Cable & Plug Casing & Impeller	V				

This annual report confirms the equipment identified above was tested and conformed to EN14960-2019 Standards at the time of test, however it does not confirm the equipment will continue to conform to the above standard for the full 12 months prior to t

Signed:	1	Saull	Print:	4- South
Signed	1 /	12000		

Pat Test Return Flap